

Application


The AM-708 500 ohm resistor converts a 4 to 20 mA signal to a 2 to 10 Vdc signal.

AM-708

500 Ohm Resistor

Specifications

- Actuators: MS40-7043, MS40-7073, MS40-7153, MS40-717X, MS40-6083, MS40-6153 and MS40-6343.
- Wire leads.



Application


The AM-709 damper shaft position indicator is used in short shaft applications to show the shaft position.

AM-709

Damper Shaft Position Indicator

Specifications

- Actuators: MX40-704X.
- Shaft sizes:
 - Up to 3/4" diameter round shaft
 - Up to 1/2" square for square shaft.
- Secured to actuator with retaining ring.



Application

The AM-710 universal clamp is used to clamp the actuator to 3/4" diameter round shafts, 3/8" to 5/8" hex shafts, or 1/2" square shafts. The AM-710 is required whenever the AM-676 shaft extension is used.

AM-710

Universal Clamp

Specifications

- Actuators: MX40-704X.
- Shaft sizes:
 - Up to 3/4" diameter round shafts.
 - 3/8" to 5/8" hex shafts.
 - Up to 1/2" square for square shafts.
- Secured to actuator with retaining ring.



Application

The AM-711 crankarm kit attaches to the actuator and provides a crankarm for shafts up to 1/2" diameter.

AM-711

Crankarm Kit

Specifications

- Actuators: MX40-704X.

